Vehicle Vin must be updated with the sales code of the added accessory in order to enable system functionality. Using the DealerCONNECT website and a StarSCAN diagonstic tool, complete the procedure below:
<ul> <li>Log on to https://dealerconnect.chrysler.com</li> </ul>
<ul> <li>In the "Vehicle Option" screen under the "Global Claims System" category in the "Service" tab, enter vehicle VIN and add sales code(s) noted below as a "Dealer Installed Option".         <ul> <li><u>XRV</u> (Rear Seat Video System)(I and II)</li> <li>(RD9) (II Only)</li> <li>(RF5) (II Only)</li> </ul> </li> </ul>
<ul> <li>Confirm that the new sales code has been successfully added to the VIN.</li> </ul>
<ul> <li>With the StarSCAN diagnostic tool connected to both the internet (via Ethernet port or wireless connection) and the vehicle, follow the steps below:</li> </ul>
IN THE INITIAL START UP SCREEN
• PRESS VEHICLE PREPARATION
• TOGGLE DOWN AND HIGHLIGHTRESTORE VEHICLE CONFIGURATION
• PRESS <b>START</b>
• PRESS <b>NEXT&gt;</b>
• IF NECESSARY, SELECT PROPER VEHICLE LINE AND MODEL YEAR AND PRESS <b>NEXT&gt;</b>
CONFRIM CORRECT SELECTION AND PRESS     NEXT>
• ENTER VEHICLE VIN USING ON -SCREEN KEYBOARD OR CONFIRM THAT AUTO-FILLED VIN PLATE AND PRESS <b>NEXT&gt;</b>
• PRESS <b>OK</b>
• ENTER USER ID, PASSWORD AND DEALER CODE USING ON-SCREEN KEYBOARD AND PRESS <b>OK</b>
• WAIT FOR VEHICLE CONFIGURATON DATA TO BE DOWNLOADED AND THEN PRESS NEXT>
• PRESS <b>NEXT&gt;</b>
CONFIRM THAT VEHICLE CONFIGURATION HAS BEEN PROGRAMMED SUCCESSFULLY
• NOTE ON-SCREEN INSTRUCTIONS AND PRESSFINISH 67

IN THE INITIAL START UP SCREEN
• PRESS ECU VIEW
• TOGGLE DOWN AND HIGHLIGHT TIPMCGW CENTRAL GATEWAY
• PRESS MISC FUNCTIONS
• TOGGLE DOWN, SELECT DVD PLAYER / VIDEO SETTING
CONFIRM / CONFIGURE TO APPLICABLE LOCATION
• TOGGLE DOWN, SELECT CHANGE COUNTRY CODE
CONFIRM / CONFIGURE TO CORRECT COUNTRY OF USE
VALIDATION PROCESS IN THE INITIAL START UP SCREEN
• PRESS ECU VIEW
• TOGGLE DOWN AND HIGHLIGHT TIPMCGW CENTRAL GATEWAY
• PRESS MORE OPTIONS
• PRESS ECU DETAILS
• PRESS CONFIG INFO
• TOGGLE DOWN, VERIFY:
VES3SET COUNTRY CODESET DVD REGION CODE(IS THE CORRECT REGION CODE. I.E. 1 FOR NORTH AMERICA)
*** after exit you must reboot the car computer by taking out the battery for 10 minutes ***
68